

# UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 10

1200 Sixth Avenue, Suite 900 Seattle, Washington 98101-3140

August 3, 2010

Reply To:

OEA-095

#### **MEMORANDUM**

SUBJECT: Review of current groundwater data from the Lakewood Ponders Corner Superfund site to determine if EPA needs to perform a mini-investigation to explain the increases in PCE from MW-16A

FROM:

Bernie Zavala, Hydrogeologist, LG, LHG

Office of Environmental Assessment

TO:

Chris Cora, Remedial Project Manager

Office of Environmental Cleanup

I did receive your email regarding technical support on the Superfund site Lakewood Ponders Corner. I have in the past had some involvement with this site and I'm familiar with this site. This site is not assigned to me. I did review the information that Guy Barrett, Ecology sent to you and the information that was sent is not complete to make the assessment re: the mini-investigation. Guy Barrett is asking EPA to perform a mini investigation to explain the increases in concentration for MW-16A. The better question to ask has the conceptual site model (CSM) change to explain the increase in MW-16A?

#### Past & Current CSM for the Lakewood Ponder site:

Source area & Contamination: Dry Cleaners - Plaza Cleaners contamination being chlorinated solvents, PCE found in a septic tank behind the Plaza Cleaners. The dry cleanser is located northeast of the Production Wells H1 &H2 of the Lakewood Water District. See Ecology's Figure 1, Lakewood Plaza Cleaners Sampling Locations and EPA's figure 2.

Geology: The site remediation has been limited to the Vashon Glaciation and within that drift only four geologic units has been impacted by the remediation. The Geologic units for this site starting at the ground surface are the permeable sands and gravels of the recessional outwash deposits (Steilacom gravels). Then the Vashon Till-"B-zone" MW-20B is located in this zone consisting of silt and clay-rich till low permeability. Below


this depth is the "A-zone" a permeable advance outwash deposit, it is the primary aquifer. The production wells H1 and H2 and MW-16A are screened in this zone. See EPA's figure 3 which is a North to South cross-section from the Plaza Cleaners to H1 and H2.

Flow Direction of Groundwater: The conclusions from the RI and an article in the Ground Water Monitoring Review dated, Fall 1983 stated that the wells H1&H2 reverses the groundwater flow direction from the natural flow toward Gravelly Lake in a Northwest direction to the pumping centers of H1&H2. The area that is influence by these wells can be referred to as the zone of contribution. EPA's figure 7 shows a 2-D capture zone based on site specific data. This capture zone graphic was produced by EPA's Wellhead Protection Areas (WHPA) module being RESSQC module. This graphic delineated flow lines to the well screens for H1 & H2 in the "A-zone" or advance Outwash.

Remedial Action: The septic tank was removed and vapor extraction took place at this location to remedy the unsaturated soils. The groundwater as explained above was being captured by H1 and H2 and an air stripping towers were built to remove the volatile Organic Compounds from the groundwater. The Vashon Till has high levels of PCE in the groundwater that has continued to impact the advance outwash aquifer around H1 and H2. Based on data that was forward to EPA from Ecology only monitoring wells 20B and 16A are still being impacted by a secondary source in the Till unit and Wells H1 and H2 are containing and treating the groundwater contamination.

Conclusion: The CSM has not change and as long as Wells H1 and H2 are pumping and treating the groundwater, no change is needed. It appears that a mini-investigation is not needed at this time based on the CSM. The concentrations of PCE in MW-16A are increasing but the source location is understood and the pathways are known and has been cut off through treatment. It would be good to have some additional information on the extraction rates for both H1 & H2 to confirm the hydraulics or the capture area.

Please let me know if you have any questions on the above information.



Ecology's Figure 1 (taken from Guy Barrett, Ecology email dated 7/23/2010)





Figure 2 Enlarged Base Map - Lakewood/Ponders Site Monitoring Wells and Lakewood Water District Wells H1 and H2 (Data from EPA Region 10 Monitoring Well Database, Extraction Date: 9/12/94)



(adapted from CH2HH111, Ponders Corner Peasibility Study)




Figure 7 Lakewood/Ponders Corner Site: 11 Year Capture Zones of Lakewood Water District Wells H1 and H2 in Yellow, Monitoring Wells in Red

### References

Keely, J.F. and Wolf, F., "Field Applications of Chemical Time-Series Sampling", Ground Water Monitoring Review, Fall 1983.

US Environmental Protection Agency, July 1985, Remedial Investigation and Feasibility Study Ponder's Corner, Washington. EPA 112-OL22. CH2MHill, Bellevue, Washington.

U.S. Environmental Protection Agency, March 1991, A Modular Semi-Analytical Model for the Delineation of Wellhead Protection Areas, version 2.0, WHPA.

Appendix. Summary of Sample Results (ug/L) from January 1991 to June 2010

Well	Ja	nuary 19	991		May 199	)]	No	vember	1991		May 199	)2	De	cembe	r 199	)2	
Number	PCE	TCE	cis-1,2-DCE	PCE	TCE	cis-1,2-DCE	PCE	TCE	cis-1,2-DCE	PCE	TCE	cis-1,2-DCE	PCE	TCE	C	cis-1,2-I	DCE
MW-16A	28	1 J	2.4 J	26	0.6 J	2	2.7 J	1 U	0.6 J	7	1 U	1	9 J	0.3	J	0.8	J
MW-20A	1 U	1 U	I U	0.4 J	1 U	1 U	0.4 J	1 U	1 U	0.5 J	1 U	1 U	0.8 J	1	UJ	1	UJ
MW-20B	1100 D	18	33	752	16	30	120	2.6 J	6.7	940	13	32	340 J	14	J	20	J
MW-21	2.1 J	1 U	1 J	2	1 U	0.7 J	2.2 J	1 U	1.0 J	2	1 U	0.6 J	2	0.2	J	0.3	J
MW-27	1 U	1 U	1 U	I U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 UJ	1	UJ	1	UJ
MW-28A														-		-	65
MW-31	1 J	1 U	1.9 J	0.6 J	1 U	2	0.9 J	1 U	2.2 J	0.8 J	1 U	1	0.5 J	1	UJ	0.9	J
MW-32	1 J	1 U	1.1 J	1	1 U	2	0.6 J	1 U	0.6 J	0.7 J	1 U	1	0.7 J	1	UJ	0.5	J
MW-41	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 UJ	1	UJ	1	UJ
MW-19A			-				1 U	0.5 J	1 U				1 UJ	1	UJ	1	UJ
MW-33			323					44			37					7.7	
MW-40	1 U	1 U	1 U	.55	==		1 U	1 U	1 U	75		**	1 UJ	1	UJ	I	UJ
H1/H2																	-1

Well			May 199	93	De	ecember	1993		April 199	94	No	vember	1994		July 1993	5
Number	PCE		TCE	cis-1,2-DCE	PCE	TCE	cis-1,2-DCE	PCE	TCE	cis-1,2-DCE	PCE	TCE	cis-1,2-DCE	PCE	TCE	cis-1,2-DCE
MW-16A	44		10 U	2 J	13	0.3 J	0.7 J	33	0.6	1.4	9.7	0.3 J	0.5 J	27	0.5 J	0.8 J
MW-20A	10	U	10 U	10 U	0.3 J	1 U	1 U	0.4	0.2 U	0.2 U	0.3 J	I U	1 U	0.4 J	1 U	I U
MW-20B	700	D	12	21	187	50 U	8.2 J	472	8.6 J	12.6	86	50 U	3 J	340 D	8.4	17
MW-21	1	J	10 U	10 U	1.6	1 U	0.4 J	1.5	0.2 J	0.3	1.8	0.2 J	0.3 J			24
MW-27	10	U	10 U	10 U	1 U	1 U	1 U	0.2 U	0.2 U	0.2 U	1 U	1 U	1 U	1 U	1 U	I U
MW-28A	,			77.5	3.5			14-						1 U	1 U	1 U
MW-31	10	U	10 U	10 U	0.8 J	1 U	1.2 J	0.7	0.2 U	1.0	0.8 J	1 U	1	0.6 J	1 U	0.5 J
MW-32	10	U	10 U	10 U	0.7 J	I U	0.6 J	0.7	0.2 U	0.6	0.6 J	1 U	0.5 J	0.7 J	1 U	0.5 J
MW-41	10	U	10 U	10 U	I U	1 U	_1 U	0.2 U	0.2 U	0.2 U	1 U	1 U	I U	1 U	1 U	1 U
MW-19A			**		1 U	0.4	1 U	0.2 U	0.5	0.2 U				1 U	0.4 J	1 U
MW-33			-	44	- 22		22	-4	25	22		22	23	1 U	1 U	1 U
MW-40					1 U	1 U	1 U	0.2 U	0.2 U	0.2 U		-		I U	1 U	1 U
H1/H2							**							9	0.3 J	I U

U = The analyte was not detected at or above the reported result.

J = The analyte was positively identified. The associated numerical result is an estimate.

UJ = The analyte was not detected at or above the reported estimated result.

D = Analysis performed at secondary dilution.

-- = Not tested

# Appendix (cont.). Summary of Sample Results (ug/L) from January 1991 to June 2010

Well		Ja	nuary	19	96			July 1996	)	J	anuary 19	997		July 199	7	Fe	bruary 19	98
Number	PCE		TCE		cis-1,2-	DCE	PCE	TCE	cis-1,2-DCE	PCE	TCE	cis-1,2-DCE	PCE	TCE	cis-1,2-DCE	PCE	TCE	cis-1,2-DCE
MW-16A	47	E	0.8	J	1.5		43	0.7 J	1.9	54	1.1	3.1	47	0.7 J	2.5	36	0.7 J	2 J
MW-20A	0.2	J	1	U	1	U	0.4 J	1 U	1 U	0.4 J	1 U	1 U	0.3 J	1 U	2 U	0.4 J	1 U	1 U
MW-20B	353		7.2		15		387	7.6	15	373	100 U	6.4 J	222	4	6.4	456	7 J	12
MW-21	-				-	2	Well Deco	mmissione	ed									
MW-27	1	U	1	U	1	U	I U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	2 U	1 U	1 U	1 U
MW-28A	1	U	1	U	1	U	Well Deco	mmission	ed									
MW-31	0.6	J	1	U	0.7	J							0.9 J	1 U	0.9 J			22
MW-32	0.8	J	1	U	0.6	J	211											
MW-41	1	U	1	U	1	U						22		122				-
MW-19A												-7575	1 U	0.3 J	2 U			( <u>4-4</u> -
MW-33					2.		I U	1 U	1 U			***	1 U	1 U	2 U			
MW-40					-								**					
H1/H2	8.4		0.2	J	0.2	J	0.14 J	1 U	1 U	18	0.4 J	0.4 J	8.8	0.3 J	0.6 J	11	0.4 J	0.3 J

Well		July 199	8	Ja	nuary 19	999	A	August 19	99	Ja	anuary 20	000	A	ugust 20	00
Number	PCE	TCE	cis-1,2-DCE	PCE	TCE	cis-1,2-DCE	PCE	TCE	cis-1,2-DCE	PCE	TCE	cis-1,2-DCE	PCE	TCE	cis-1,2-DCE
MW-16A	30	1 U	1.5 J	H-4	(mm)		22	0.4 J	1.1	40	0.7 J	1.9	22	0.3 J	0.7
MW-20A	0.6 J	1 U	1 U	1 U	2 U	1 U	0.8 J	2 U	1 U	0.2 J	2 U	1 U	0.1 J	2 U	1 U
MW-20B	575 D	10	23	708	5.2	12	722	8.4 J	16 J	184	6	13	648	200 U	100 U
MW-27	0.05 J	1 U	1 U	1 U	2 U	1 U	1 U	2 U	1 U	1 U	2 U	1 U	1 U	2 U	1 U
MW-31						***	0.9 J	2 U	0.4 J	***	77				
MW-32									-				0.8 J	2 U	1 U
MW-41		- m/m	**	(ee				**	***		22		1 U	2 U	1 U
MW-19A						***	1 U	0.4 J	1 U						
MW-33	1 U	1 U	1 U	7,021			1 U	2 U	1 U		-	***	1 U	2 U	1 U
MW-40	iee:	***		1,77			**					**	1 U	2 U	1 U
H1/H2	10	1 U	0.1 J	1.5	1 U	1 U	5.2	0.2 J	1 U	10	1 U	1 U	8.7	0.03 J	1 U

U = The analyte was not detected at or above the reported result.

J = The analyte was positively identified. The associated numerical result is an estimate.

D = Analysis performed at secondary dilution.

E = The concentration of the associated value exceeds the known calibration range.

-- = Not tested

# Appendix (cont.). Summary of Sample Results (ug/L) from January 1991 to June 2010

Well	J	anuary 2	001	A	ugust 20	001	Fe	ebruary 2	002	A	August 20	002	Fe	ebruary 20	003
Number	PCE	TCE	cis-1,2-DCE	PCE	TCE	cis-1,2-DCE	PCE	TCE	cis-1,2-DCE	PCE	TCE	cis-1,2-DCE	PCE	TCE	cis-1,2-DCE
MW-16A	31	0.4 J	1	25	0.3 J	0.7 J	47	0.8 J	2.3	22	0.3 J	0.8 J	59 J	0.2 J	2.4
MW-20A	0.2 J	1 U	1 U	1 U	2 U	1 U	77						1 U	1 U	1 U
MW-20B	493	6.6 J	12	486	8.2	18	248	200 U	100 U	371	8.5	16	230	100 U	100 U
MW-27	1 U	1 U	1 U	1 U	2 U	1 U	1 U	2 U	1 U	1 U	2 U	1 U	1 U	1 U	1 U
MW-31			***	0.4 J	2 U	0.3 J				100		**		-	
MW-32		**			-	ne.		**							22
MW-41		(422)		22		4.00		***		**				177	-
MW-19A				I U	0.3 J	1 U					-	**			
MW-33				I U	2 U	1 U				1 U	1 U	I U			
MW-40								-							
H1/H2	11	0.2 J	1 U	6.8	0.2 J	1 U	12	0.2 J	0.2 J	6.1	1 U	1 U	1.3	1 U	1 U

Well	Sep	tember :	2003		June 200	14	No	vember 2	2004		June 200	05	N	ovember 2	005
Number	PCE	TCE	cis-1,2-DCE	PCE	TCE	cis-1,2-DCE	PCE	TCE	cis-1,2-DCE	PCE	TCE	cis-1,2-DCE	PCE	TCE	cis-1,2-DCE
MW-16A	26	0.3 J	0.5 J	30	0.4 J	0.8 J	48	1 U	1.4	80.3	1.3	2.8	43	0.69 J	1.0 J
MW-20A	0.1 J	1 U	1 U	0.2 J	1 U	1 U	0.3 J	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
MW-20B	239	5.4 J	12	344	6.5 J	15	241	6.7	13	413	6.6	12	555	6.4	11
MW-27	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
MW-31	0.5 J	1 U	0.1 NJ	77	~~					0.53 J	I U	1 U			**
MW-32				(4/4)			~~			1.4	1 U	I U			1929
MW-41			321	122		++		+	**	1 U	1 U	1 U		55	
MW-19A	1 U	0.4 N	J I U				-			1 U	0.57 J	1 U			
MW-33	1 U	1 U	I U		***	-	177			I U	1 U	1 U			22
MW-40	**		(22)	122				***	**	1 U	I U	I U	.55	-55	277
H1/H2	6.4	0.2 N	J 1 U	7.9	0.24 J	0.1 J	2.6	1 U	1 U	14	0.31 J	1 U	6.4	1 U	1 U

U = The analyte was not detected at or above the reported result.

J = The analyte was positively identified. The associated numerical result is an estimate.

-- = Not tested

Appendix (cont.). Summary of Sample Results (ug/L) from January 1991 to June 2010

Well		May 200	6	Sep	otember 2	2006		June 200	7	0	ctober 20	007		May 200	8
Number	PCE	TCE	cis-1,2-DCE	PCE	TCE	cis-1,2-DCE	PCE	TCE	cis-1,2-DCE	PCE	TCE	cis-1,2-DCE	PCE	TCE	cis-1,2-DCE
MW-16A	124	1.8	4.6	29	0.3 J	0.48 J	83	1.2	2.5	24	1 U	0.64 J	55	1.2	2.8
MW-20A	1 U	1 U	1 U	1 U	1 U	I U	2 U	2 U	2 U	2 U	1 U	1 U	1 U	1 U	1 U
MW-20B	216	4.2	6.6	518	5.6	11	204	4.4	7.8	491	7.5	15	143	5.5	12
MW-27	1 U	1 U	1 U	1 U	1 U	1 U	2 U	2 U	2 U	2 U	1 U	1 U	1 U	1 U	1 U
MW-31			92	1227			1.6 J	2 U	2 U					<del></del>	
MW-32	77			200				***	**			~~			
MW-41					***										
MW-19A						22	2 U	1.2 J	2 U						
MW-33	I U	1 U	1 U				2 U	2 U	2 U			77	1 U	1 U	1 U
MW-40				**											
LPMW-2	9.9	1 U	I U				4.8	1 U	1 U	927	22	22	2.5	1 U	1 U
LPMW-3	1 U	1 U	1 U				2 U	1 U	1 U	300		7.7			
H1/H2	7.3	0.22 J	1 U	4.8	1 U	1 U	5.2	2 U	2 U	3.8	1 U	1 U	9.6	1 U	1 U

Well	October 2008		008		June 200	9	No	vember 2	2009		June 201	0
Number	PCE	TCE	cis-1,2-DCE	PCE	TCE	cis-1,2-DCE	PCE	TCE	cis-1,2-DCE	PCE	TCE	cis-1,2-DCE
MW-16A	31	0.45 J	0.6 J	67	0.94 J	2.2	28	0.52 J	0.83 J	85	1.3	1.6
MW-20A	1 U	1 U	I U	1 U	1 U	l U	0.64 J	1 U	1 U	1 U	1 U	1 U
MW-20B	258	4.5	y	160	4.1	7.4	250	4.7	9.6	130	3.7	6.3
MW-27	I U	1 U	1 U	I U	1 U	1 U	1 U	1 U	1 U	1 U	1 U	1 U
MW-31	(44)											
MW-32			77						99	1.8	1 U	1 U
MW-41		-	<del>777</del> -		***	***			No. or	1 U	1 U	1 U
MW-19A	***		**	I U	1 U	1 U						
MW-33				I U	1 U	1 U				1 U	1 U	1 U
MW-40		7.7	27.	170								**
LPMW-2				4.1	I U	1 U	11	1 U	1 U	4.4	1 U	1 U
H1/H2	5.1	1 U	1 U	6.8	1 U	l U				4.3	1 U	1 U

U = The analyte was not detected at or above the reported result.

J = The analyte was positively identified. The associated numerical result is an estimate.

-- = Not tested